

System: Fire-Lite Model: MS 9200 UDLS

DEVICE TEST RESULTS

(Attach additional sheets if required)

Address		Device Type	Location	Test Results
1M001	Monitor	Module	Annunciator Reset switch	
1M002	Monitor	Module	Annunciator Silence switch	
1M003	Monitor	Module	Annunciator Acknowledge switch	
1M004	ALARM	PULL	FRONT ENTRANCE	
1M005	ALARM	PULL	BACK EXIT	
1M007	SUPV.	TAMPER VALVE	BACK STAIRWAY	
1M008	ALARM	WATERFLOW	BACK STAIRWAY	
1M010	Monitor	Module	BASE ALARM RESET	
1M011	Relay	Module	DOOR RELEASE	
1M20	ALARM	MONITOR	ALARM FROM ANACOSTIA BLDG.	
1D006	ALARM	SMOKE-PHOTO	MECHANICAL RM	
1D007	ALARM	SMOKE PHOTO	PANTRY ROOM	
1D008	ALARM	SMOKE-PHOTO	ABOVE FACP	
1D033	ALARM	SMOKE-PHOTO	BARJ ROOM	

NOTE: The Local Fire alarm within the BARJ area is functional as intended.

Somehow, The main building is not receiving any types of signal from this Panel. Mr. Norman Hayes is aware of the current issue and will work with their contracted vendor to check the problem. I advised the CSO on duty that the Fire alarm is not dialing out to central station and call Mr.Norman if fire alarm is activated. And dial 911 for any smoke or fire within the area.