



EMSL Analytical, Inc.

10752 & 10768 Baltimore Avenue Beltsville, MD 20705

Tel/Fax: (301) 937-5700 / (301) 937-5701

<http://www.EMSL.com> / beltsvillelab@emsl.com

EMSL Order: 192306904

Customer ID: MAXX50

Customer PO:

Project ID:

Attention: Kiki Muse
Maxximus Environmental
1010 Rockville Pike
Rockville, MD 20852

Phone: (301) 838-2730

Fax: (301) 838-2732

Received Date: 08/04/2023 16:27 PM

Analysis Date: 08/07/2023

Collected Date: 08/04/2023

Project: DC COURTS RECORDER OF DEEDS

Test Report: Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) Performed by EPA 40 CFR Part 763 Appendix A to Subpart E

Sample	Location	Volume (Liters)	Area Analyzed (mm ²)	Non Asb	Asbestos Type(s)	#Structures ≥0.5μ < 5μ	≥5μ	Analytical Sensitivity (S/cc)	Asbestos Concentration (S/mm ²)	(S/cc)
8-4-23-IWA-01	IN MIDDLE OF RM 300/ WORK AREA-01	1235.00	0.0650	0	None Detected	0	0	0.0048	<15.00	<0.0048
192306904-0001										
8-4-23-IWA-02	BETWEEN RMS 300 & 302/ WORK AREA-01	1235.00	0.0650	0	None Detected	0	0	0.0048	<15.00	<0.0048
192306904-0002										
8-4-23-IWA-03	BETWEEN RMS 301 & 303/ WORK AREA-01	1235.00	0.0650	0	None Detected	0	0	0.0048	<15.00	<0.0048
192306904-0003										
8-4-23-IWA-04	IN NORTH-END RM 305/WORK AREA-01	1235.00	0.0650	0	None Detected	0	0	0.0048	<15.00	<0.0048
192306904-0004										
8-4-23-IWA-05	IN SOUTH--END RM 309/WORK AREA-01	1235.00	0.0650	0	None Detected	0	0	0.0048	<15.00	<0.0048
192306904-0005										
8-4-23-IWA-06	WEST-END OF RM 319/WORK AREA-02	1235.00	0.0650	0	None Detected	0	0	0.0048	<15.00	<0.0048
192306904-0006										
8-4-23-IWA-07	EAST-END OF RM 319/WORK AREA-02	1235.00	0.0650	0	None Detected	0	0	0.0048	<15.00	<0.0048
192306904-0007										
8-4-23-IWA-08	MIDDLE OF RM 319/WORK AREA-02	1235.00	0.0650	0	None Detected	0	0	0.0048	<15.00	<0.0048
192306904-0008										
8-4-23-IWA-09	NORTH-END OF RM 319/WORK AREA-02	1235.00	0.0650	0	None Detected	0	0	0.0048	<15.00	<0.0048
192306904-0009										
8-4-23-IWA-10	SOUTH-END OF RM 319/WORK AREA-02	1235.00	0.0650	0	None Detected	0	0	0.0048	<15.00	<0.0048
192306904-0010										

Analyst(s)

Emily Baker (10)

Emily C. Baker Asbestos Laboratory Manager
or other approved signatory

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. This report must not be used to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. Results reported in structures/cm3 are not covered by the laboratory's NVLAP accreditation. Measurement of uncertainty available upon request.

Samples analyzed by EMSL Analytical, Inc. Beltsville, MD NVLAP Lab Code 200293-0

Initial report from: 08/07/2023 13:13 PM